


# CORNER RECORD

Document Number APN 047-021-23&53

City of MILL VALLEY County of Marin California.

Brief Legal Description: D.N. 92-98681 & 93-108428 LOT 11 OF 10 R.M. 10 & 18 O.S. 43



### CORNER TYPE:

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES

[Optional]  
 N> \_\_\_\_\_  
 E> \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev> \_\_\_\_\_

CORNER:----- Left as found  Found & Tagged  Established  Reestablished  Rebuilt

Identification & Type of Corner Found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND EXISTING MONUMENTS: SHOWN ON REVERSE

A description of the physical condition of the monument as found and as set or reset: SET REBAR & CAP,

RCE# 18200, AT LOCATIONS AS SHOWN ON REVERSE.

### SURVEYOR'S STATEMENT

The corner record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on AUGUST 1 1998


Signed: Douglas J. Matteson LS or RCE # 18200

### COUNTY SURVEYORS STATEMENT

This corner record was received: Oct. 6  
1998

and filed OCTOBER 7  
1998

Signed: John M. Woolley  
Title: DEPUTY



COUNTY SURVEYOR'S  
COMMENT \_\_\_\_\_