

# CORNER RECORD

Document Number APN 047-021-27

City of MILL VALLEY County of Marin California.

Brief Legal Description: Lot 6 Douglas Dr. Gardens RM Bk. 10 - Pg 10 Marin Co Records


### CORNER TYPE:

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES

[Optional]  
 N > \_\_\_\_\_  
 E > \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev > \_\_\_\_\_

CORNER:----- Left as found  Found & Tagged  Established  Reestablished  Rebuilt

Identification & Type of Corner Found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found existing Lot Corners as noted on Reverse

A description of the physical condition of the monument as found and as set or reset:

SET 5/8" REBAR & CAP, RCE# 18200, AT LOCATIONS SHOWN ON REVERSE.

### SURVEYOR'S STATEMENT

The corner record was prepared by me or under my direction in conformance with  
 the Land Surveyors' Act on JUNE 1 2002

Signed: Douglas J. Matteson LS or RCE # 18200



### COUNTY SURVEYORS STATEMENT

This corner record was received: JUNE 13, 2002

and filed JULY 9, 2002

Signed Craig Tackabery Title: DEPUTY



COUNTY SURVEYOR'S COMMENT \_\_\_\_\_