


**CORNER RECORD**

Document Number \_\_\_\_\_

City of Mill Valley

County of Marin, California

Brief Legal Description Being Lots 27 & 28, Map of Camp Tamalpais (3 RMC)



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey Nov. 2006

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found Monuments as shown on Record of Survey (7-05-11) See Page 2

A description of the physical condition of the monument as found and as set or reset: Set 3/4" Iron

Pipe with Plastic Cap "LS 5814", See Page 2

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 1/26/07

Signed [Signature] P.L.S. or R.C.E. No. 5814

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received JANUARY 29, 2007

and examined and filed FEBRUARY 1, 2007

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_

