


# CORNER RECORD

Document Number APN 047-112-63

City of MILL VALLEY

County of Marin California

Brief Legal Description: LOT 1 AS SHOWN ON 21 RM 9 MARIN CO. RECORDS



### CORNER TYPE:

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES

[Optional]  
 N> \_\_\_\_\_  
 E> \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev> \_\_\_\_\_

CORNER:---- Left as found  Found & Tagged  Established  Reestablished  Rebuilt

Identification & Type of Corner Found: Evidence used to identify or procedure used to establish or reestablish the corner:  
FOUND WELL MONUMENTS AS SHOWN ON 21-RM-9

A description of the physical condition of the monument as found and as set or reset: SET REBAR & CAP, RCE# 18200, AT LOCATIONS SHOWN ON REVERSE.

### SURVEYOR'S STATEMENT

The corner record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JULY 2 1997

Signed: [Signature] LS or RCE# 18200



### COUNTY SURVEYORS STATEMENT

This corner record was received: JULY 14 1997

and filed JULY 15 1997

Signed: [Signature] Title: Deputy



COUNTY SURVEYOR'S COMMENT \_\_\_\_\_

\_\_\_\_\_  
 \_\_\_\_\_