


CORNER RECORD

Document Number A.P. # 47-112-67

City of MILL VALLEY

County of MARIN, California

Brief Legal Description LOT 5, GLEN GRAE SUB UNIT 1 21 RM 9



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey \_\_\_\_\_
- Control
- Property
- Other

A.P. 47-112-67  
COORDINATES  
(Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

THE PROPERTY CORNERS WERE REESTABLISHED  
FROM THE STREET MONUMENTS AS DELINEATED  
ON THE SUBDIVISION MAP 21 RM 9

A description of the physical condition of the monument as found and as set or reset:

SEE THE LEGEND ON PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on SEPTEMBER 1997

Signed Lawrence P. Doyle L.S. or R.C.E. Number 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 1 1997 and examined and filed DECEMBER 2 1997.

Signed John M. Wooley Title DEPUTY



County Surveyor's Comment \_\_\_\_\_