


CORNER RECORD

Document Number APN 047-124-36

City of MILL VALLEY

County of MARIN, California

Brief Legal Description LOT 8, 14 RM 37



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 7-14-10

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND STANDARD STREET MONUMENTS AS SHOWN ON 14 RM 37 AND ON REVERSE


A description of the physical condition of the monument as found and as set or reset:

SET REBARS W/TAG, PLS 5296, SET HUB & TAG PLS 5296 AND SET TACK & TAG PLS 5296 AS SHOWN ON REVERSE

SURVEYOR'S STATEMENT

This Corner record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JULY 23, 2010

Signed [Signature] P.L.S. or R.G.E. No. PLS 5296



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPTEMBER 13, 2010

and examined and filed OCTOBER 7, 2010

Signed [Signature] P.L.S. or R.G.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____

