


CORNER RECORD

Document Number AP# 47-132-02

City of Mill Valley (Vicinity)

County of MARIN, California

Brief Legal Description Lot 13, 3 RM 27



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey July 10, 1998

COORDINATES
(Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PLAT, SHEET 2 OF 2.
REFERENCE 35 ROS 27.

A description of the physical condition of the monument as found and as set or reset:

SEE PLAT, SHEET 2 OF 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JULY 14, 1998.

Signed [Signature] L.S. or R.C.E. Number LS 6649



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 6 1998 and examined and filed AUGUST 7 1998.

Signed John M. Woolley Title DEPUTY



County Surveyor's Comment _____