



JERRICO ASSOCIATES

SUITE 27
77 MARK DRIVE
SAN RAFAEL, CA 94903

7481


CORNER RECORD

Document Number 48-051-37

City of Mill Valley

County of Marin, California

Brief Legal Description Lot 2 8 P. M. 49



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey March 12, 2003

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found points in 40' R/W (L) (M) (N) as iron pipe
and tag LS 2535 in 8 PM 49

A description of the physical condition of the monument as found and as set or reset:
(A) (B) (C) (D) (E) (F) (G) Set rebar and cap LS 3887.
(X) (Y) (Z) Set plastic pipe and cap (plug) LS 3887

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on March 12, 2003

Signed [Signature] P.L.S or R.C.E. No. LS 3887



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received July 11, 2003

and examined and filed July 22, 2003

Signed [Signature] P.L.S or R.C.E. No. 30212

Title DEPUTY



County Surveyor's Comment _____