| CORNER RECORD |) | Document Number | A.P.# 048-132-10 |
|--|--|------------------------------|---------------------------|
| City of MILL VALLE | <u>.Y</u> | County ofMAR | IN, California |
| Brief Legal Description | LOT 10, BLOCK 1, 5 R.M. 5 | • | |
| | CORNER TYPE COO Government Corner Contro | ol | NAD27 NAD83 NAD83 |
| | Meander ☐ Proper Rancho ☐ Other Date of Survey | rty 🛛 Elev. — Vert. Datum | |
| Corner- Left as found 🛛 | Found and tagged Establish | ed 🗌 Reestablished 🛛 | Rebuilt |
| REESTABLISHED L | orner found: Evidence used to identify or nOT 10, BLOCK 1, 5 R.M. 54, AS UND PER 2007 M. 90, AS SHOW | SHOWN ON 2007 M. 90 | , |
| A description of the physical | condition of the monument as found and | l as set or reset: SEE SI | HEET 2. |
| This Corner Record was prep | PYOR'S STATEMENT pared by me or under my direction in conf | | SEO LAND SUP |
| the Land Surveyor's Act on Signed | JULY 10, P.L.S. or R.C.E. No. | 2013 P.L.S. 4694 | — No. 4694 Exp. 9/30/13 ★ |
| COUNTY SU This Corner Record was recei | RVEYOR'S STATEMENT (ved SEP'TEMBER (| 24, 2013 | THE OF CALL FORMY |
| and examined and filed | NOVEMBER 12, 2 | 7821 | RICHARD G. SIMONITCH |
| Title DEP. CO. SURV | | , - | No. 7821 |
| County Surveyor's Comment | | | T CALITY CALITY |
| | | | |
| | | | |
| | _ | | |

