


CORNER RECORD

Document Number 48-156-15
County of MARIN, California

City of MILL VALLEY
Brief Legal Description PARCEL 3, 6 PM 2



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 11/8/2001

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISH THE SOUTHWESTERLY CORNER OF PARCEL 3
PER 6 PM 2 & MISC. LINE POINTS. SEE SKETCH ON REVERSE SIDE.
THIS SURVEY FOUND ORIGINAL POINTS OF SAID 6 PM 2
TO RECREATE PARCEL MAP POSITIONS.

A description of the physical condition of the monument as found and as set or reset:

set 1/2" rebar with PLS CAP 5379 AFFIXED TO THE
TOP & DRIVEN FLUSH WITH SURROUNDING GRADE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on NOVEMBER 9th 2001

Signed Douglas J. Scranton P.L.S or R.G.E. No. PLS 5379
RENEWAL 6-30-2001



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 15, 2001

and examined and filed _____

Signed Craig Tackabery P.L.S or R.G.E. No. 7128

Title DEPUTY



County Surveyor's Comment _____

BY: 845 OLIVE AVE. NOVATO, CA
Prepared
DJ SCRANTON SURVEYING