

CORNER RECORD

APN 048-202-37

Document No. _____


City of MILL VALLEY County of Marin, California

Brief Legal Description Lot 9, & PORTION OF LOTS 8 & 10, BLOCK 3, 4 RM 92 & 70S 46

CORNER TYPE

COORDINATES

(Optional)



Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey November 20, 2002

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure to establish or reestablish the corner:
Established property corners per found property corners shown on herein sht. 2 and per Record of Survey, Recorded in book 7 of Surveys Page 46, June 27, 1968, County of Marin.

A description of the physical condition of the monument as found and as set or reset:
Set 3/4" iron pipe w/ plastic cap, LS 5461 as shown on herein sheet 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors Act on November 20, 2002.

Signed *David William Keane* PLS Number 5461



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 25, 2002 and examined and filed NOVEMBER 27, 2002.

Signed *Craig Tackabery* Title DEPUTY

County Surveyor's Comments _____

