


CORNER RECORD

Document Number A.P. # 48-212-18
County of MARIN, California

City of MILL VALLEY
Brief Legal Description PARCEL 1 3 PM 5



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 3-24-00

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 1/2" I.P.s & TAGS L.S. 7251, AS SHOWN ON
1999 MAPS 256, AND ON REVERSE.

FOUND 1/2" IRON PIN, AS SHOWN ON 1999 MAPS 256, AND
ON REVERSE.


A description of the physical condition of the monument as found and as set or reset:

SET 3/4" I.P.s & TAGS L.S. 5296, AS SHOWN ON REVERSE.
SET MAG NAILS & TAGS L.S. 5296, AS SHOWN ON REVERSE.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors Act on 3-27-00

Signed [Signature] L.S. or R.C.E. Number 5296



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 4-7-2000 and examined

and filed 4-01-2000
Signed [Signature] Title DEPUTY



County Surveyor's Comment _____