


CORNER RECORD

Document Number APN 48 - 232 - 12 # 56

City of MILL VALLEY

County of MARIN, California

Brief Legal Description LOT 2 AS DEPICTED UPON 22 0.5.67



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey \_\_\_\_\_
- Control
- Property
- Other

COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
REESTABLISH THE MOST NORTHEASTERLY CORNER OF LOT 2 AS  
DEPICTED UPON 22 05 67 FROM EXISTING STREET MONUMENTS ON  
LATTIE LANE AS SAID MONUMENTS ARE DEPICTED UPON SAID  
22 05 67

A description of the physical condition of the monument as found and as set or reset:  
SET 1/2" REBAR WITH CAP PLS 5379


SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MARCH 30<sup>th</sup> 1998.  
 Signed [Signature] L.S. or R.C.E. Number PLS 5379  
renewal 6-30-00



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 31 1998 and examined and filed APRIL 3 1998.  
 Signed [Signature] Title DEPUTY



County Surveyor's Comment \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

PREPARED BY: D.J. SCRANTON SURVEYING, 845 OLIVE AVE. NOVATO, CA. 94945

JN 98/6