## **CORNER RECORD**

Agency Index Dru # 19 - 110

Document Number ADJ 048-232-47

				, California
Brief Legal DescriptionSTANDARD COUNTY MONUMENT SHOWN ON 20 RS 07.				
CORNER TYPE		COORDINATES (Optional)  N E		
	Governmen  Meander  Rancho	Corner Control Property Other	Units Metric  Horizontal Datum	U.S. Survey Foot
			ZoneEpoch Date	
	Date of Survey	Vuly 15, 2019		esources Code §§8801-8819 esources Code §§8890-8902
PLS Act Ref.:	8765(d)	8771	8773	Other:
Corner/ Monument:	Left as found Found and tagged	Established  Reestablished	Rebuilt Referenced	Pre-Construction Post-Construction
Narrative of corner identified and monument as found, set, reset, replaced, or removed:  See sheet #2 for description(s):				
FOUND STANDARD COUNTY MONUMENT SHOWN ON 20 RS 07 NEAR LOT 51 AS SHOWN ON MAP 4 RM 76. SET FOUR REFERENCE TIES; RE-ESTABLISHED WITH COUNTY OF MARIN WELL MONUMENT PER UCS DWG #300. (SEE ATTACHED SKETCH) NO DETERMINATION WAS MADE AS TO THE VALIDITY OF THE MONUMENT SHOWN HERON OR ITS RELATION TO PROPERTY LINES IN THE AREA.				
SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with				
the Professional Land Surveyors' Act on  O/20/27  Signed  P.L.S. or R.C.E. No. 9292  P.L.S. or R.C.E. No. 9292				
COUNTY SURVEYOR'S STATEMENT				
This Corner Record was received  and examined and filed  Signed  P.L.S. OROE. No. 8176  Title  County Surveyor's Comment  County Surveyor's Comment				

