
CORNER RECORD

Agency Index
DPW # 19 - 10 1
Document Number ADJ 048-232-57 ADJ

MARIN , California
MONUMENT SHOWN ON 20 RS 07.

City of	MILL VALLEY	County of _	MARIN	, California
Brief Legal Description STANDARD COUNTY MONUMENT SHOWN ON 20 RS 07.				
CORNER TYPE		COORDINATES (Optional) N E		
	Governmen Meander Rancho	t Corner X Control Property Other	Elevation Units Metric Horizontal Datum	U.S. Survey Foot
	Date of Survey	July 15, 2019	ZoneEpoch Vertical Datum	n Date
	g Bate of Garvey	JULY 15 , 2019	Complies with Public Re	esources Code §§8801-8819 esources Code §§8890-8902
PLS Act Ref.:	8765(d)	8771	8773	Other:
Corner/ Monument:	Left as found Found and tagged	Established Reestablished	Rebuilt Referenced	Pre-Construction Post-Construction
Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s):				
FOUND STANDARD COUNTY MONUMENT SHOWN ON 20 RS 07 NEAR LOT 32 AS SHOWN ON MAP 4 5 76. SET FOUR REFERENCE TIES; RE-ESTABLISHED WITH COUNTY OF MARIN WELL MONUMENT PER UCS DWG #300. (SEE ATTACHED SKETCH) NO DETERMINATION WAS MADE AS TO THE VALIDITY OF THE MONUMENT SHOWN HERON OR ITS RELATION TO PROPERTY LINES IN THE AREA.				
SURVEYOR'S STATEMENT				
This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on				
SEMERAD *				
Signed P.L.S. or R.C.E. No. 9292				
COUNTY SURVEYOR'S STATEMENT				
This Corner Record was received and examined and filed Colored PARK No. 8176				
Signed P.L.S. W. D. INO.				
County Surveyor's Comment				
- Julity July Oy Ol 3				COMMUNICATION OF THE PARTY OF T

BPELSG-2016 Page 1 of 2



COUNTY OF

DEPARTMENT OF PUBLIC WORKS SURVEY SECTION

SCALE: 1"=10'

JOB No. 2019-28