


CORNER RECORD

Document Number APN 48-232-57

City of MILL VALLEY County of MARIN, California

Brief Legal Description LOT 'A' AS DEPICTED UPON 21 05 83



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
REESTABLISHED THE NORTHEAST, SOUTHEAST AND SOUTHWEST CORNERS OF
LOT 'A' AS DEPICTED UPON 21 05 83 FROM EXISTING STREET MONUMENTS
ON LATTIE LANE AS SAID MONUMENTS ARE DEPICTED UPON SAID 21 05 83.

A description of the physical condition of the monument as found and as set or reset:
AT SOUTHEAST AND SOUTHWEST CORNERS SET 1/2" REBAR WITH CAP PLS 5379
AT NORTHEAST CORNER SET PK NAIL DRIVEN IN PAVEMENT.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on MARCH 30 19 98.

Signed Douglas J. Scranton L.S. or R.C.E. Number PLS 5379
Renewal 6.30.00



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 31 19 98 and examined

and filed APRIL 3 19 98.
 Signed John M. Wooley Title DEPUTY



County Surveyor's Comment _____

PREPARED BY: D.J. SCRANTON SURVEYING 845 OLIVE AVENUE NOVATO, CA. 94945

JN 98/8