
## **CORNER RECORD**

Agency Index DPW #19 - 107

Document Number ADJ 048-232-70 ADJ

MARIN California

City of	MILL VALLEY	County of _	MARIN	, California
Brief Legal DescriptionNAIL AND TAG SHOWN ON 2013 RS 04.				
CORNER TYPE		COORDINATES (Optional)  N E		
	Government Meander Rancho Date of Survey	Corner Control Property Other	Elevation Units	U.S. Survey Foot ute
PLS Act Ref.:	8765(d)	8771	8773	Other:
Corner/ Monument:	Left as found Found and tagged	Established  Reestablished	Rebuilt Referenced	Pre-Construction Post-Construction
Narrative of corner identified and monument as found, set, reset, replaced, or removed:  See sheet #2 for description(s):				
FOUND NAIL AND BRASS TAG STAMPED "L.S. 4694" SHOWN ON 2013 RS 04 NEAR LOT 25 AS SHOWN ON MAP 4 RM 76. SET FOUR REFERENCE TIES; RE-ESTABLISHED WITH 3/8" MAG SPIKE. (SEE ATTACHED SKETCH) NO DETERMINATION WAS MADE AS TO THE VALIDITY OF THE MONUMENT SHOWN HERON OR ITS RELATION TO PROPERTY LINES IN THE AREA.  SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with				
SEMERAD				
Signed P.L.S. or Re.E. No. 9292  P.L.S. or Re.E. No. 9292  P.L.S. or Re.E. No. 9292				
COUNTY SURVEYOR'S STATEMENT				
This Corner Record was and examined and filed Signed  Title	6/20/2 1. Pat Ly Surve	P.L.S. <b>@P.C.E</b> . No	2019	TRACY W. PARK NO. 8176  * * * * * * * * * * * * * * * * * *



BPELSG-2016

DEPARTMENT OF PUBLIC WORKS SURVEY SECTION

RECORD