


# CORNER RECORD

Document Number A.P. # 48-233-04

City of MILL VALLEY

County of MARIN, California

Brief Legal Description Lots 7 & 8 Block 3; Fairview park Sub No 2 < 4 RM 82 >



### CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey \_\_\_\_\_
- Control
- Property
- Other

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found existing street monuments per ROS Bk 23 p 53 and reset corner per data on map.

A description of the physical condition of the monument as found and as set or reset: Set 1/2" rebar and Plastic cap #18200.

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on April 27 1995.

Signed Douglas J. Matteson R.C.E. Number 18200



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received May 3 1995 and examined and filed May 4 1995.

Signed John M. Wooley Title \_\_\_\_\_



County Surveyor's Comment \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_