CORNER RECORD

Agency Index
Document Number ADJ 048-233-57

MARIN

NDENT RESURVEY T.1N. R.6W. M.D.M.

City of	MILL VALLEY	County of _	MARII	N, California
Brief Legal Descrip	otion BLM DISC	SHOWN ON DEPE	NDENT RESURVEY	/ T.1N., R.6W., M.D.M.
	Government Meander	Corner X Control Property	NElevation Units Metric	NATES (Optional) E. U.S. Survey Foot
	Rancho Date of Survey	June 15, 2019	Vertical Datum Complies with Public	och Date Resources Code §§8801-8819 Resources Code §§8890-8902
PLS Act Ref.:	8765(d)	8771	8773	Other:
Corner/ Monument:	Left as found Found and tagged	Established Reestablished	Rebuilt Referenced	Pre-Construction Post-Construction
FOUND 3" BLM BRASS DISC STAMPED POINT NUMBER 446 SHOWN ON DEPENDENT RESURVEY OF THE G.G.N.R.A. 1985 T.1N.,R6W., M.D.M. NEAR LOT 2 AS SHOWN ON MAP 4 RM 82. SET FOUR REFERENCE TIES; RE-ESTABLISHED WITH COUNTY WELL MONUMENT PER UCS DWG #300. (SEE ATTACHED SKETCH) NO DETERMINATION WAS MADE AS TO THE VALIDITY OF THE MONUMENT SHOWN HERON OR ITS RELATION TO PROPERTY LINES IN THE AREA.				
SURVEYOR'S STATEMENT				
This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on P.L.S. or R.C.E. No. 9797 COUNTY SURVEYOR'S STATEMENT COUNTY SURVEYOR'S STATEMENT				
COUNTY SURVEYOR'S STATEMENT				
This Corner Record was and examined and filed Signed Title County Surveyor's	6/20/20 L Part My Survey	6055 7, 28	8176	TRACY W. PARK NO. 8176 * OF CALIFORNIA

