## **CORNER RECORD**

Agency Index

Document Number ADJ 048-233-77

California

City of	MILL VALLEY	County of _	MARIN	, California
Brief Legal Description STANDARD COUNTY MONUMENT SHOWN ON 20 OS 07.				
CORNER TYPE		RNER TYPE	COORDINATES (Optional)	
	Government Meander Rancho Date of Survey	Corner Control Property Other	`	U.S. Survey Foot
PLS Act Ref.:	8765(d)	8771	8773	Other:
Corner/ Monument:	Left as found Found and tagged	Established  Reestablished	Rebuilt Referenced	Pre-Construction Post-Construction
Narrative of corner identified and monument as found, set, reset, replaced, or removed:  See sheet #2 for description(s):				
FOUND STANDARD COUNTY MONUMENT SHOWN ON 20 OS 07 NEAR LOT 16 AS SHOWN ON MAP 4 RM 76. SET FOUR REFERENCE TIES; RE-ESTABLISHED WITH COUNTY OF MARIN WELL MONUMENT PER UCS DWG #300. (SEE ATTACHED SKETCH) NO DETERMINATION WAS MADE AS TO THE VALIDITY OF THE MONUMENT SHOWN HERON OR ITS RELATION TO PROPERTY LINES IN THE AREA.				
SURVEYOR'S STATEMENT  This Corner Record was prepared by me or under my direction in conformance with  JOHN R. SEMERAD				
the Professional Land S		P.L.S. or R.C.E. No.	9292	* No. 9292 *  OF CALIFORNIA
,	COUNTY SURVEY	OR'S STATEMENT		
This Corner Record was and examined and filed Signed Title County Surveyor's	1. Parker Ly Surver	P.L.S. 60REE. No.	 8176	TRACY W. PARK NO. 8176

- SET WOOD HUB WITH MAG NAIL AND WASHER STAMPED "MARIN COUNTY SURVEYOR" ON SHOULDER OF ROAD. REF 5:

OF MARIN

DEPARTMENT OF PUBLIC WORKS SURVEY SECTION

SCALE: 1"=10'

JOB No. 2019-28

CORNER RECORD