

CORNER RECORD

Document Number A.P.# 049-072-11

City of MILL VALLEY

County of MARIN, California

Brief Legal Description LOT 25 32 O.S. 77

CORNER TYPE

COORDINATES (Optional)

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 02/12/03

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner: Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
REESTABLISHED THE EASTERLY LINE OF LOT 25 FROM FOUND POINTS PER 32 O.S. 77.

A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on FEBRUARY 13 2003

Signed Lawrence P. Doyle P.L.S. or R.C.E. No. P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 21, 2003

and examined and filed FEBRUARY 26, 2003

Signed Craig Tackabery P.L.S. or R.C.E. No. 7128

Title DEPUTY

County Surveyor's Comment _____

