


**CORNER RECORD**

Document Number APN 049-112-12

City of MILL VALLEY

County of MARIN, California

Brief Legal Description PER RECORD OF SURVEY 27/S/84



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 10 DEC 2001

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner -- Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

SEE PAGE 2

A description of the physical condition of the monument as found and as set or reset:

SEE PAGE 2

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on DECEMBER 11 2001

Signed \_\_\_\_\_ P.L.S or R.C.E. No. 6784




**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received DECEMBER 14, 2001

and examined and filed DECEMBER 17, 2001

Signed \_\_\_\_\_ P.L.S or R.C.E. No. 7128

Title DEPUTY



County Surveyor's Comment \_\_\_\_\_