CORNER RECORD

Document Number APN 049-151-14 Unincorporated County of Marin , California Brief Legal Description As shown on that Record of Survey filed in Book 2004 of Maps, at Page 107 **COORDINATES (Optional) CORNER TYPE** N. E. Government Corner Control Elevation Meander Property Units Metric U.S. Survey Foot Rancho Other Horizontal Datum Epoch Date Date of Survey December 18, 20% Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: X 8765(d) 8771 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Post-Construction Found and tagged Referenced Reestablished Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Found two iron pipes, PLS 4694 marking the southerly line. Set three line points for construction setbacks and re-set northerly corner on top of wood wall. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on December 22, 2020 P.L.S. or R.C.E. No. 7950 Signed **COUNTY SURVEYOR'S STATEMENT** 01/05/2021 This Corner Record was received and examined and filed TRACY W. P.L.S. 000 BOOD No. 8/7/6 Signed PARK NO. 8176 Title

Agency Index DPW#21-031

County Surveyor's Comment