


CORNER RECORD

Document number A.P.N. 049-154-06

City of MILL VALLEY County of MARIN, California

Brief Legal Description LOT 26A AS SHOWN UPON RECORD OF SURVEY
2004 O.S. 22, MARIN COUNTY RECORDS



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner-- Left as found found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
UTILIZED MONUMENTS AS SHOWN UPON 2004 O.S. 22 AS A BASIS OF BEARINGS
TO MONUMENT PROPERTY CORNER AND PROPERTY LINE POINTS OF LOT 26A
AS SHOWN UPON SAID MAP.

A description of the physical condition of the monument as found and as set or reset.
MONUMENTS PER 2004 O.S. 22 MEASURED PER SAID MAP, AND MONUMENTS SET
ARE SHOWN UPON ATTACHED DIAGRAM

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on December 14 2012.


Signed [Signature] L.S. Number 7744



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 14, 2012 and examined
and filed JANUARY 15, 2013

Signed [Signature] Title DEPUTY CO. SURVEYOR



County Surveyor's Comment _____

SCALE: 1" = 30'

