


**CORNER RECORD**

Document Number APN 049-182-53

City of MILL VALLEY

County of MARIN, California

Brief Legal Description PARCEL A, RECORD OF SURVEY LOTS E, F, G & H TAMALPAIS WOODS ADD: SUB 1 (12 RS 88)



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND R.R. SPIKE PER 12 RS 88 ; AND FOUND REBAR WITH CAP , LS 2897 PER 12 RS 88 .

A description of the physical condition of the monument as found and as set or reset: SET NAIL & TAG, RCE 30465, SET GINNEY, SET 3/4" IP & PLASTIC PLUG, RCE 30465, AND SET CROSS CUT; SEE PAGE 2

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 6/12/03

Signed Jay H P.L.S or **(R.C.E)** No. 30465



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received JULY 2, 2003

and examined and filed JULY 10, 2003

Signed C P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_