


CORNER RECORD

Document Number A.P. 049-193-02

City of MILL VALLEY

County of MARIN, California

Brief Legal Description LOT 5 BLOCK F, 2 R.M. 120



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

**COORDINATES
(Optional)**

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

THE PROPERTY CORNERS WERE REESTABLISHED
FROM THE MONUMENTS SHOWN ON THE
RECORD OF SURVEY BOOK 1999 OF MAPS PAGE 6

A description of the physical condition of the monument as found and as set or reset: _____

SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 5/19 1999.

Signed Lawrence P. Doyle L.S. or R.C.E. Number P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 2 1999 and examined and filed AUGUST 10 1999.

Signed [Signature] Title DEPUTY



County Surveyor's Comment _____

