


CORNER RECORD

Document Number APN 49-205-08

City of MILL VALLEY and County of MARIN, California

Brief Legal Description: A PORTION OF LOT 28, BLOCK A MAP ENTITLED "MAP OF BLOCKS A,B,C,D, AND E OF TAMALPAIS VALLEY, MARIN CO, CALIFORNIA", PER BOOK 2 MAPS 119.



CORNER TYPE

Government Corner [] Control []
Meander [] Property [X]
Rancho [] Other []

Date of Survey 10/22/12

COORDINATES (Optional)

N: _____
E: _____
Zone: _____ NAD 27 [] NAD 83 []
Elev: _____
Vert. Datum: NGVD29 [] NAVD88 []
Meas. Units: Metric [] Imperial [X]

CORNER -- LEFT AS FOUND FOUND AND TAGGED ESTABLISHED REESTABLISHED REBUILT

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND MONUMENTS PER RECORD OF SURVEY, BOOK 2004 PAGE 22

FOUND 5/8" REBAR AND CAP LS7744 AND NAIL AND BRASS TAG LS 7744

FOUND MONUMENT PER RECORD OF SURVEY, BOOK 2006 PAGE 55

FOUND REBAR AND CAP RCE 18200

A description of the physical condition of the monument as found and as set or reset: _____

SET POINTS AS SHOWN ON REVERSE.

SURVEYOR'S STATEMENT:

The corner record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on NOVEMBER 1ST 2012

Signed: Serena L Goodwin L.S.# 8708



COUNTY SURVEYOR'S STATEMENT:

The corner record was received NOVEMBER 20, 2012

and examined and filed JANUARY 15, 2013

Signed: Richard G. Simonitch R.C.E. or L.S. No. 7821

Title: DEPUTY COUNTY SURVEYOR



COUNTY SURVEYOR'S COMMENT: _____

