


CORNER RECORD

Document Number APN 49-227-26

City of Mill Valley County of Marin, California

Brief Legal Description Parcel 'C' Parcel Map 3 PM 61



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found four (4) monuments at angle points on the northerly boundary and
three (3) monuments at angle points on the southerly boundary of
Parcel "C" 3 PM 61


A description of the physical condition of the monument as found and as set or reset: _____

Set 3/4" iron pipe tagged "RCF 18221" at the most northerly
corner of Parcel "C" 3 PM 61

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyors' Act on JULY 27, 2000

Signed [Signature] L.S. or R.C.E. Number 18221



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 8-1-2000 19__ and examined
and filed 8-3-2000 19__

Signed [Signature] Title DEPUTY



County Surveyor's Comment _____