3Y:	
PREPARE	

	Document Number AFN 30-012-01
City of Mill Valley	County of Marin Californi
Brief Legal Description Lots 10 &11, Block	County of Marin Terraces, 5 RM 29
Government Corner Meander Rancho	Control
Date of Survey Apri	1 28,1998 Elev
Corner — Left as found [Found and tagged [☐ Established ☐ Reestablished ☒ Rebuilt ☐
on Identification and type of corner found: Evidence used to it	dentify or procedure used to establish or reestablish the comer:
Reestablished the Northwest corner	of Lot 11, Block 300, Subv. 3 of Marin
Y Terraces, 5 RM 29 as said corner -	
o set per this survey was established	from existing street manual
West California Avenue as shown upo	n 10 oc 40 Grid
o apo	n 19 03 49. Said monuments were
$_{\infty}$ established from found points of sa	id 16 OS 41 and represent the
$\stackrel{\circ}{\sim}$ A description of the physical condition of the monument :	as found and as set or reset
(continued) centerline of West Cali	fornia as depicted and determined per
16 OS 41. Refer to sketch on page	2.
	LS cap 5379 affixed to top and driven
flush with existing ground A large	a make a few and driven
flush with existing ground. A large	e metal rence post was set next to
the pipe as an aid for locating the	pipe as it was set in the ground.
SURVEYOR'S STATEMENT	LAND
This Corner Record was prepared by me or under my d	irection in conformance with the state of th
	No. 5379 No. 5379 Renewal 6-30-00
COUNTY SURVEYOR'S STATEM	CALIFO CALIF
This Corner Record was received AUGUST 3	19 98 and examined
and filed AWGUST 3 1998.	SEAL MA GOODS
Signed M. Wooly T	itle DEPUTY No. 26450
County Surveyor's Comment	OF CALLECTION
	A STATE OF THE STA