


CORNER RECORD

Document Number 50.012.03

City of MILL VALLEY

County of MARIN, California

Brief Legal Description Lot 8, Block 300, SUB 3, MARIN TERRACES (SRM29)



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey MAY 7, 1998
- Control
- Property
- Other

COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Reestablish the NORTHWESTERLY CORNER & the South EASTERLY CORNER of Lot 11, Block 300 Subv. 3 of MARIN TERRACES (SRM29), AS SAID CORNERS WERE ESTABLISHED UPON 160541. CORNERS SET FROM CENTERLINE STREET MONUMENTS OF 190549 ON W. CALIFORNIA AVE; SAID MONUMENTS SET USING POINTS FOUND ON 160541

A description of the physical condition of the monument as found and as set or reset:  
NORTHWEST CORNER: set 1/2" rebar w/ PLS CAP LS 5379  
Affixed to TOP & DRIVEN flush with NATURAL GRADE  
SOUTH EAST CORNER: set LEAD PLUG & TAG LS 5379  
IN CONCRETE DRIVEWAY / see sketch on REVERSE side

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on MAY 18<sup>th</sup> 19 98.

Signed Douglas J. Scranton L.S. or R.C.E. Number LS 5379  
renewal 6-30-98



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUGUST 3 19 98 and examined

and filed AUGUST 3 19 98.

Signed John M. Woolley Title DEPUTY



County Surveyor's Comment \_\_\_\_\_

PREPARED BY: DOUGLAS J. SCRANTON, SURVEYING, NAVATO, CALIFORNIA

DO SCRANTON