


CORNER RECORD

Document Number A.P. # 50-052-57

City of MILL VALLEY (AREA) County of MARIN, California

Brief Legal Description S.E. CORNER PARCEL C 16 P.M. 30
A.P. 50-052-57



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey _____

**COORDINATES
(Optional)**

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

REESTABLISHED THE CORNER FROM
EXISTING MONUMENTS AS SHOWN ON
16 P.M. 30

A description of the physical condition of the monument as found and as set or reset: _____

SET NAIL AND TAG P.L.S. 4694 ON HEADWALL

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on APRIL 23 1998.

Signed Lawrence P Doyle L.S. or R.C.E. Number PLS 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 21 1998 and examined

and filed JULY 22 1998.

Signed John M. Woolley Title DEPUTY



County Surveyor's Comment _____