


**CORNER RECORD**

Document Number AP N<sup>o</sup> 050-062-13

City of MILL VALLEY

County of MARIN, California

Brief Legal Description LOT 11 BLK 3 5 Rm 28



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

N: \_\_\_\_\_  
E: \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner -- Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

RETRACEMENT OF 5 Rm 28  
2004 RS 80

A description of the physical condition of the monument as found and as set or reset:

FOUND STD STREET MONUMENTS  
SET 1/2" REBAR & CAP LS 6344

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on FEB. 2009

Signed [Signature] P.L.S or R.C.E. No. 6344



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received JUNE 4, 2009

and examined and filed JULY 1, 2009

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment \_\_\_\_\_

