


CORNER RECORD

Document Number APN 050-141-34

City of MILL VALLEY

County of Marin California.

Brief Legal Description: LOTS 11& 25 & PTN 12&24; MARIN HTS. SUB. "C" 4-RM-104



CORNER TYPE:

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES [Optional]

N> _____
 E> _____
 Zone _____ Datum _____
 Elev> _____

CORNER:----- Left as found Found & Tagged Established Reestablished X Rebuilt

Identification & Type of Corner Found: Evidence used to identify or procedure used to establish or reestablish the corner:

FND. EXISTING PLASTIC CAPS; RCE 18200 AS SHOWN ON 24-OS-15

A description of the physical condition of the monument as found and as set or reset: SET REBAR & CAP RCE 18200 AT LOCATIONS SHOWN ON REVERSE.

SURVEYOR'S STATEMENT

The corner record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on JULY 9 1997 _____

Signed: Douglas J. Matteson TS or RCE # 18200




COUNTY SURVEYORS STATEMENT

This corner record was received: AUGUST 21 1997 _____

and filed AUGUST 22 1997 _____

Signed: John M. Wooley Title: DEPUTY



COUNTY SURVEYOR'S COMMENT _____

