


# CORNER RECORD

Document Number 050-171-02

City of MILL VALLEY

County of Marin California

Brief Legal Description: LOTS 15 & 16, MARIN HTS. SUB. "C": 4 RM 104; LANDS OF JOHNSON



### CORNER TYPE:

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES

[Optional]  
 N> \_\_\_\_\_  
 E> \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev> \_\_\_\_\_

CORNER:----- Left as found  Found & Tagged  Established  Reestablished  Rebuilt

Identification & Type of Corner Found: Evidence used to identify or procedure used to establish or reestablish the corner:


Found existing corners per corner record 050-171-01 & set adjacent corners as shown on the reverse

A description of the physical condition of the monument as found and as set or reset: Set 1/2" Rebar & Plastic Cap  
RCE #18200.

### SURVEYOR'S STATEMENT

The corner record was prepared by me or under my direction in conformance with  
 the Land Surveyors' Act on August 1997

Signed: Douglas J. Matteson LS or RCE # 18200 18200



### COUNTY SURVEYORS STATEMENT

This corner record was received: OCTOBER 3, 1997

and filed OCTOBER 3 1997

Signed: John M. Wooley Title: Deputy



COUNTY SURVEYOR'S COMMENT \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_