


CORNER RECORD

Document Number AP# 50-211-01

City of MILL VALLEY

County of MARIN, California

Brief Legal Description LOTS 11 & 12 ~ 4 RM 99



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 11-04-04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND MONUMENTS PER 4 PM 54 AND CORNER RECORD
FILED 8/10/98, AS SHOWN ON REVERSE.

A description of the physical condition of the monument as found and as set or reset:

SET 3/4" I.P., TAGGED P.L.S. 5296 AND SET PK AND TAG P.L.S. 5296.

AP# 50-211-01

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on NOVEMBER 6, 2004

Signed [Signature] P.L.S or R.C.E. No. P.L.S. 5296



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 24, 2004

and examined and filed DECEMBER 22, 2004

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR



County Surveyor's Comment _____

