


CORNER RECORD

Document Number 51-111-20

City of MILL VALLEY County of Marin, California

Brief Legal Description Lot 19, Block 214, 4 RM 44



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 3-9-01

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

see Exhibit "A" on reverse

A description of the physical condition of the monument as found and as set or reset: _____

see Exhibit "A" on reverse

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 9-18-02

Signed Paul Canumay P.L.S or R.C.E. No. 3272




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPTEMBER 19, 2002

and examined and filed SEPTEMBER 19, 2002

Signed Ce P.L.S or R.C.E. No. 7128

Title DEPUTY



County Surveyor's Comment _____