


# CORNER RECORD

Document Number 051-121-58

City of MILL VALLEY

County of Marin California

Brief Legal Description: DN 99-049628



### CORNER TYPE:

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey \_\_\_\_\_

### COORDINATES

[Optional]  
 N> \_\_\_\_\_  
 E> \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev> \_\_\_\_\_

CORNER:----- Left as found  Found & Tagged  Established  Reestablished  Rebuilt

Identification & Type of Corner Found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND EXISTING MONUMENTS: SHOWN ON REVERSE

A description of the physical condition of the monument as found and as set or reset: SET REBAR & CAP,

RCE# 18200, AT LOCATIONS SHOWN ON REVERSE.

### SURVEYOR'S STATEMENT

The corner record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on NOVEMBER 2000 \_\_\_\_\_

Signed: Douglas J. Matteson LS or RCE # 18200



### COUNTY SURVEYORS STATEMENT

This corner record was received: NOVEMBER 6, 2000 \_\_\_\_\_

and filed NOVEMBER 7, 2000 \_\_\_\_\_

Signed: John M. Wooley Title: DEPUTY



COUNTY SURVEYOR'S COMMENT \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_