


**CORNER RECORD**

Document Number APN 51-131-42

City of Mill Valley

County of Marin, California

Brief Legal Description 211 California Ave - APN 51-131-42 - LOTS 33-35 Bk 201 4RM44



**CORNER TYPE**

- Government Corner  Control
- Meander  Property
- Rancho  Other
- Date of Survey \_\_\_\_\_

**COORDINATES (Optional)**

- N. \_\_\_\_\_
- E. \_\_\_\_\_
- Zone \_\_\_\_\_ NAD27  NAD83
- NAD83 Epoch \_\_\_\_\_
- Elev. \_\_\_\_\_
- Vert. Datum: NGVD29  NAVD88
- Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See Sketch on Back

A description of the physical condition of the monument as found and as set or reset:

See Sketch on Back

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on Jan 25 2002

Signed Michael A. Brogan P.L.S or R.C.E. No. LS 5767




**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received JANUARY 29, 2002

and examined and filed JANUARY 30, 2002

Signed [Signature] P.L.S or R.C.E. No. 7128

Title DEPUTY



County Surveyor's Comment \_\_\_\_\_