


CORNER RECORD

Document Number A.P.# 51-131-51

City of MILL VALLEY

County of MARIN, California

Brief Legal Description 215 CALIFORNIA AVE, 310553, APN 51-131-51
LOTS 38, 39, 40, 41 & 42 BLOCK 201 4 RH 44



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES
(Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
See Sketch

A description of the physical condition of the monument as found and as set or reset:
See Sketch

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on January 30 1998.

Signed Michael A. Brogan L.S. or R.C.E. Number LS5767



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 4 1998 and examined and filed FEBRUARY 6 1998.

Signed [Signature] Title _____



County Surveyor's Comment _____