


**CORNER RECORD**

Document Number A.P.N. 051-251-31

City of VICINITY OF ALMONTE/MILLVAUER County of MARIN, California

Brief Legal Description LOT 12, BLOCK 21 PER 4 R.M. 11



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey MARCH 14, 2002

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

= SEE OVER =

A description of the physical condition of the monument as found and as set or reset:


= SEE OVER =

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyor's Act on APRIL 22, 2002

Signed David Contreras P.L.S. or R.C.E. No. 5065



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received APRIL 30, 2002

and examined and filed MAY 3, 2002

Signed C P.L.S. or R.C.E. No. 7128

Title DEPUTY



County Surveyor's Comment \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_