

CORNER RECORD

Document Number A.P.# 051-272-27

City of MILL VALLEY

County of MARIN, California

Brief Legal Description PARCEL B 12 P.M. 100

CORNER TYPE

Government Corner Control

Meander Property

Rancho Other

Date of Survey 10/30/02

COORDINATES (Optional)

N. _____

E. _____

Zone _____ NAD27 NAD83

NAD83 Epoch _____

Elev. _____

Vert. Datum: NGVD29 NAVD88

Meas. Units: Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
ESTABLISHED NORTHERLY PROPERTY LINE BASED ON FOUND POINTS PER 12 P.M. 100

A description of the physical condition of the monument as found and as set or reset: SEE SHEET 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyor's Act on OCTOBER 30 2002

Signed Lawrence P. Doyle P.L.S. or R.C.E. No. P.L.S. 4694



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 12, 2002

and examined and filed NOVEMBER 13, 2002

Signed [Signature] P.L.S. or R.C.E. No. 7128

Title DEPUTY



County Surveyor's Comment _____