


CORNER RECORD

Document Number _____

City of MILL VALLEY County of MARIN, California

Brief Legal Description LOT #539 KAY PARK UNIT FOUR (7 RM 55)



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey _____
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND MONUMENTS IN STREET AS PER PARCEL MAP (11 PM 18)

A description of the physical condition of the monument as found and as set or reset:
SET 1/2" REBAR WITH PLASTIC CAPS RCE 30465;
SEE PAGE 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on July 29 1996.

Signed [Signature] L.S. or R.C.E. Number RCE 30465



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JULY 29 1996 and examined and filed 7-30 1996.

Signed [Signature] Title DCS



County Surveyor's Comment _____