


CORNER RECORD

VICINITY City of MARIN CITY

Document Number A.P.N. 052-082-05

County of MARIN, California

Brief Legal Description LOT 79 PER 11 R.M. 46



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 11-24-97

COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

- SEE OVER -

A description of the physical condition of the monument as found and as set or reset:

- SEE OVER -

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on DECEMBER 2 1997.


Signed David Montano L.S. or R.C.E. Number LS 5065



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 4 1997 and examined and filed DECEMBER 9 1997.

Signed [Signature] Title DEPUTY



County Surveyor's Comment \_\_\_\_\_