


CORNER RECORD

Document Number A.P. # 55-081-01

City of TIBURON County of MARIN, California

Brief Legal Description LOT 22 7 R.M. 48 526 Comstock Drive 55-081-01



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey _____

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See Sketch


A description of the physical condition of the monument as found and as set or reset:

See Sketch

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on August 31 19 99.

Signed Michael A. Brogan L.S. or R.C.E. Number LS 5767



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received September 1 19 99 and examined and filed SEPTEMBER 2 19 99.

Signed John M. Wooley Title Deputy



County Surveyor's Comment _____