


CORNER RECORD

Document Number 55-142-08City of TiburonCounty of Marin, CaliforniaBrief Legal Description Survey of portion of southerly line of Lot 12, Del Mar Estates Unit 1, 8 RM 102

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey August 15, 2007

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NAVD88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Standard Subdivision Monuments on Fellpa Court, 8 RM 102

A description of the physical condition of the monument as found and as set or reset:

#4 rebar and plastic cap stamped "L.S. 3887 as shown set

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 25, 2007

Signed [Signature] P.L.S or R.C.E. No. L.S. 3887

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 16, 2007
and examined and filed DECEMBER 17, 2007

Signed [Signature] P.L.S or R.C.E. No. 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____

