


CORNER RECORD

Document Number A.P.N. 055-142-08
City of Tiburon County of Marin, California
Brief Legal Description Lot 12, Del Mar Estates Unit I, 7 Felipa Court, 8 RM 102.



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐

Date of Survey 30 January 2008

COORDINATES(Optional)

N. _____
E. _____
Zone _____ NAD27 ☐ NAD83 ☐
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 ☐ NADV88 ☐
Meas. Units: Metric ☐ Imperial ☐

Corner - Left as found ☐ Found and tagged ☐ Established ☒ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found Rebar and Yellow Cap L.S. 3887 (4) and Found Old Hub And Nail R.C.E. 17486 (1).
Found Standard Street Monuments (2), along Felipa Court per 8 RM 102.

A description of the physical condition of the monument as found and as set or reset: _____
Set 3/4" Iron Pipe at the most northerly corner (1), NE corner (1), along the easterly line (1),
and at the most southerly corner (1), See Exhibit "A".

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on FEBRUARY 1, 2008

Signed [Signature] P.L.S. or R.C.E. No.: 18221

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 5, 2008 and examined
and filed MARCH 3, 2008

Signed [Signature] P.L.S. or R.C.E. No.: 7128

Title COUNTY SURVEYOR

County Surveyor's Comment _____

