Document Number APN 055-142-11 CORNER RECORD City of __TIBURON MARIN County of _ California LOT 5, 8 RM 102, MAP OF DEL MAR ESTATES Brief Legal Description **CORNER TYPE** COORDINATES (Optional) □ Control Government Corner NAD27 ☐ NAD83 ☐ Zone. Property TX Meander NAD83 Epoch Other \Box Rancho Elev. Vert. Datum: NGVD29 NAVD88 Date of Survey _ Meas. Units: Metric Imperial Established X Reestablished Rebuilt Left as found Found and tagged Corner -Identification and type of comer found: Evidence used to identify or procedure used to establish or reestablish the corner: FOUND STANDARD STREET WELL MONUMENTS AS SHOWN ON 8 RM 102 AND ON REVERSE. SET 3/4" IRON PIPE AT A description of the physical condition of the monument as found and as set or reset: _ SOUTHEAST CORNER, SET PK NAIL AND TAG AT NORTHEAST CORNER IN CONCRETE AT WESTERLY BASE OF 4"x 4" AT END FENCE, AND SET 2"x2" HUB LINE POINTS ON EASTERLY LINE AS SHOWN ON REVERSE. SURVEYOR'S STATEMENT This Corner record was prepared by me or under my direction in conformance with OCTOBER 4TH the Land Surveyor's Act on _ P.L.S. or R.C.E. No. __PLS 5296 Signed _ COUNTY SURVEYOR'S STATEMENT This Corner Record was received <u>OCTOBER</u> 30, 2006 and examined and filed DECEMBER 8, 2006 P.L.S. or R.C.E. No. 7128 Signed COUNTY SURVEYOR Title County Surveyor's Comment _