

CORNER RECORD

Document Number 55-144-06

City of Tiburon

County of Marin, California

Brief Legal Description Lot 20 Map of Del Mar Estates, Unit one, 8 RM 102



CORNER TYPE

Government Corner ☐ Control ☐
 Meander ☐ Property ☒
 Rancho ☐ Other ☐
 Date of Survey March 23, 1999

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Reestablish the exterior boundary to Lot 20, Map of Del Mar Estates

Unit 1, 8 RM 102. Note: The easterly lot line of Lot 20, common to the

Land of Greene was delineated only on the main lot line(110 feet) as

shown on the diagram on page two. Corners were reestablished from

standard street monuments found on Avenida Miraflores shown per

the map of record and also delineated on page 2 .

A description of the physical condition of the monument as found and as set or reset:

Set one half inch rebar with PLS cap 5379 affixed to the top and

driven flush to exiting ground grade excepting the NW corner of

Lot 20 set lead plug with brass LS 5379 tag in stone wall.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on March 26th 19 99

Signed Douglas J. Scranton L.S. or R.C.E. Number LS 5379
 renewal date 6/30/00


COUNTY SURVEYOR'S STATEMENT

This Corner Record was received APRIL 9 19 99 and examined

and filed APRIL 12 19 99.

Signed John M. Wooley Title DEPUTY

County Surveyor's Comment _____



PREPARED BY: DJ SCRANTON SURVEYING 845 OLIVE AVENUE NOVATO, CA 94945 (415)897-2663