	-
	100
	
	÷ .
	
	2
	⋖
	12/14/2007 9:11:18 AM, 1:
	÷
	<u></u>
	÷
	<u></u>
	C
	<u></u>
	/200
	\mathbf{g}
•	ĆΛ.
	4
	Ξ-
	Ñ
	-
	_
	Ð
	3
	$\boldsymbol{\sigma}$
	ecord.dw
	Ę
	X
	ŭ
	ď
	-
	ō
	č
	Ξ
	×
	9
	ົວ
	₹
	Ó
	$\tilde{\sim}$
	₩
	~
	Ù.
	\simeq
	eyhub\JOP~`07-143\dwg\Corne
	6
	٥.
	Ø.
	う
	6
	=
	三
	>
	Ō
	2
	urve
	S
	=

CORNER TYPE Government Comer Control Earnow Control Earnow Control Contro	CORNER RECORD	Document Number APN 055-182-08	······
CORNER TYPE Government Corner Control E	City of	County of <i>Marin</i> , Ca	alifornia
Government Corner Control Endowed Property Control Render Property Control Corner Control Corner Control Corner Control Corner Control Corner	Brief Legal Description Lot 3 of Record Ma	ps, Book 13, Page 58; Marin County Records	1
Meander		N	
Date of Survey August. 2007 National Pound and tagged Established Reestablished Rebuilt Research Report Research Report Report	Meander	☐ Property ☑ Zone NAD27☐ NAD83☐ NAD83Epoch	-
Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Standard city street monuments along Hilary Drive were located and Record Angles & Distances were turned to property corners. The corner locations matched existing occupation lines. Remnants of a redwood hub at the Northeasterly corner of the property was replaced with a pipe & cap. No other evidence of existing corners were found so new markers were set at the remaining corners. A description and the physical condition of the monument as found and as set or reset: The standard city street monuments along Hilary Drive were found in good condition. Remnants of a redwood hub at the northeasterly corner was replaced with a 3/4" pipe and cap RCF12094. The Southwesterly and the Fasterly corners were set with 3/4" pipes and caps RCF12094. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Apt on October 23, 2007 Signed P.L.S. of R.C.E. No. RCF12094 P.L.S. of R.C.E. No. RCF12094 P.L.S. of R.C.E. No. 7/12 8 Signed P.L.S. of R.C.E. No. 7/12 8 Title COUNTY SURVEYOR'S Comment County Surveyor's Comment		Vert. Datum: NGVD29 NAVD88	
Standard city street monuments along Hilary Drive were located and Record Angles & Distances were turned to property corners. The corner locations matched existing occupation lines. Remnants of a redwood hub at the Northeasterly corner of the property was replaced with a pipe & cap. No other evidence of existing corners were found so new markers were set at the remaining corners. A description and the physical condition of the monument as found and as set or reset: The standard city street monuments along Hilary Drive were found in good condition. Remnants of a redwood hub at the northeasterly corner was replaced with a 3/4" pipe and cap RCE12094. The Southwesterly and the Easterly corners were set with 3/4" pipes and caps RCE12094. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed Signed P.L.S. of R.C.E. No. RCE12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filled JANUARY 2, 2008 Signed P.L.S. of R.C.E. No. 712 8 Title COUNTY SURVEYOR Comment County Surveyor's Comment	Corner - Left as found ☐ Found and to	agged □ Established ☑ Reestablished ☑ Rebuilt ☑	
Distances were turned to property corners. The corner locations matched existing occupation lines. Remnants of a redwood hub at the Northeasterly corner of the property was replaced with a pipe & cap. No other evidence of existing corners were found so new markers were set at the remaining corners. A description and the physical condition of the monument as found and as set or reset: The standard city street monuments along Hilary Drive were found in good condition. Remnants of a redwood hub at the northeasterly corner was replaced with a 3/4" pipe and cap RCE12094. The Southwesterly and the Fasterly corners were set with 3/4" pipes and caps RCE12094. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed Surveyor's Act on October 23, 2007 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.C.E. No. 7128 Title COUNTY SURVEYOR Comment County Surveyor's Comment	Identification and type of corner found: Evidence used	to identify or procedure used to establish or reestablish the corner:	
occupation lines. Remnants of a redwood hub at the Northeasterly corner of the property was replaced with a pipe & cap. No other evidence of existing corners were found so new markers were set at the remaining corners. A description and the physical condition of the monument as found and as set or reset: The standard city street monuments along Hilary Drive were found in good condition. Remnants of a redwood hub at the northeasterly corner was replaced with a 3/4" pipe and cap RCF12094. The Southwesterly and the Fasterly corners were set with 3/4" pipes and caps RCF12094. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed PLLS. of R.C.E. No. RCF12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.C.E. No. 712 8 Title COUNTY SURVEYOR'S Comment County Surveyor's Comment	Standard city street monuments along	g Hilary Drive were located and Record Angles &	÷
was replaced with a pipe & cap. No other evidence of existing corners were found so new markers were set at the remaining corners. A description and the physical condition of the monument as found and as set or reset: The standard city street monuments along Hilary Drive were found in good condition. Remnants of a redwood hub at the northeasterly corner was replaced with a 3/4" pipe and cap RCE12094. The Southwesterly and the Easterly corners were set with 3/4" pipes and caps RCE12094. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed P.L.S. of R.C.E. No. RCE12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.G.E. No. 7/12 & COUNTY SURVEYOR'S Comment County Surveyor's Comment	Distances were turned to property cor	rners. The corner locations matched existing	
A description and the physical condition of the monument as found and as set or reset: The standard city street monuments along Hilary Drive were found in good condition. Remnants of a redwood hub at the northeasterly corner was replaced with a 3/4" pipe and cap RCE12094. The Southwesterly and the Easterly corners were set with 3/4" pipes and caps RCE12094. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed Office P.L.S. of R.C.E. No. RCE12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUART 2, 2008 Signed P.L.S. of R.C.E. No. 7128 Title COUNTY SURVEYOR County Surveyor's Comment	occupation lines. Remnants of a redw	rood hub at the Northeasterly corner of the prope	<u>erty</u>
A description and the physical condition of the monument as found and as set or reset: The standard city street monuments along Hilary Drive were found in good condition. Remnants of a redwood hub at the northeasterly corner was replaced with a 3/4" pipe and cap RCE12094. The Southwesterly and the Easterly corners were set with 3/4" pipes and caps RCE12094. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed P.L.S. of R.C.E. No. RCE12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.G.E. No. 7128 Title COUNTY SURVEYOR County Surveyor's Comment	was replaced with a pipe & cap. No o	other evidence of existing corners were found so	new
The standard city street monuments along Hilary Drive were found in good condition. Remnants of a redwood hub at the northeasterly corner was replaced with a 3/4" pipe and cap RCE12094. The Southwesterly and the Easterly corners were set with 3/4" pipes and caps RCE12094. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed P.L.S. of R.C.E. No. RCE12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2 2008 Signed P.L.S. of R.G.E. No. 7128 Title COUNTY SURVEYOR Comment County Surveyor's Comment	markers were set at the remaining co	orners.	
The standard city street monuments along Hilary Drive were found in good condition. Remnants of a redwood hub at the northeasterly corner was replaced with a 3/4" pipe and cap RCE12094. The Southwesterly and the Easterly corners were set with 3/4" pipes and caps RCE12094. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed P.L.S. of R.C.E. No. RCE12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2 2008 Signed P.L.S. of R.G.E. No. 7128 Title COUNTY SURVEYOR Comment County Surveyor's Comment	A description and the physical condition of the manum	nent as found and as set or reset:	
Remnants of a redwood hub at the northeasterly corner was replaced with a 3/4" pipe and cap RCE12094. The Southwesterly and the Easterly corners were set with 3/4" pipes and caps RCE12094. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed October 23, 2007 Signed P.L.S. of R.C.E. No. RCE12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.G.E. No. 7/12 8 Title COUNTY SURVEYOR County Surveyor's Comment			*:
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed P.L.S. of R.C.E. No. RCE12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.G.E. No. 7/12 8 Title COUNTY SURVEYOR County Surveyor's Comment County Surveyor's Comment	and the second of the second o		
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed P.L.S. of R.C.E. No. RCE12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.C.E. No. 7/12 8 Title COUNTY SURVEYOR County Surveyor's Comment			
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed P.L.S. of R.C.E. No. RCE12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.C.E. No. 7128 Title COUNTY SURVEYOR'S Comment County Surveyor's Comment		o and the Easterly corners were set with 3/4 pip	<u> </u>
SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed P.L.S. of R.C.E. No. RCE12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.C.E. No. 7128 Title COUNTY SURVEYOR COMMENT County Surveyor's Comment County Surveyor's Comment	ana caps RCE12094.	· ·	
This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed P.L.S. of R.C.E. No. RCF12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.C.E. No. 7128 Title COUNTY SURVEYOR County Surveyor's Comment County Surveyor's Comment	SUDVEVOD'S STATE	MENT PROFESSIO	
This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on October 23, 2007 Signed P.L.S. of R.C.E. No. RCF12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.C.E. No. 7128 Title COUNTY SURVEYOR County Surveyor's Comment County Surveyor's Comment	1	WILLIAM & OBERRA	
Signed P.L.S. of R.C.E. No. RCE12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.C.E. No. 712 8 Title COUNTY SURVEYOR County Surveyor's Comment	This Corner Record was prepared by me or under my	direction in conformance with	. //
Signed P.L.S. of R.C.E. No. RCF12094 COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUARY 2, 2008 Signed P.L.S. of R.C.E. No. 7128 Title COUNTY SURVEYOR County Surveyor's Comment	the Land Surveyor's Act on October 23, 2007		
COUNTY SURVEYOR'S STATEMENT This Corner Record was received November 16, 2007 and examined and filed JANUART 2, 2008 Signed P.L.S. of R.C.E. No. 7/28 Title COUNTY SURVEYOR County Surveyor's Comment	Signed P.L.S. of F	R.C.E. No. <u>RCE12094</u> Exp. 3/31/0	
Signed P.L.S. of R.G.E. No. 7/28 Title COUNTY SURVEYOR County Surveyor's Comment	COUNTY SURVEYOR'S ST	TATEMENT	
Signed P.L.S. of R.G.E. No. 7/28 Title COUNTY SURVEYOR County Surveyor's Comment	This Corner Record was received November 16.	2007 PLAND	2
Signed P.L.S. of R.G.E. No. 7/28 Title COUNTY SURVEYOR County Surveyor's Comment	and examined and filed JANUARY 2, 20	DOS TACK	188
Title COUNTY SURVEYOR County Surveyor's Comment		R.C.E. No. 7128	19
	Title COUNTY SURVEYOR	No. 7128	08/1
	County Surveyor's Comment	OF CALL!	
	· · · · · · · · · · · · · · · · · · ·		
		fr-s	