


CORNER RECORD

Document Number AP # 55-221-05City of TIBURONCounty of MARIN, CaliforniaBrief Legal Description 705 HILARY DRIVE, LOT 11 - 7 RM 100, APN 55-221-05

CORNER TYPE

Government Corner ☐Meander ☐Rancho ☐

Date of Survey _____

Control ☐Property ☒Other ☐

COORDINATES (Optional)

N. _____

E. _____

Zone _____ Datum _____

Elev. _____

Corner — Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See Sketch

A description of the physical condition of the monument as found and as set or reset:

See Sketch

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on December 1 1999.Signed Michael G. Bryan L.S. or R.C.E. Number LS 5767

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received December 3 1999 and examined and filed DECEMBER 6 1999.Signed John M. Wooley Title DEPUTY

County Surveyor's Comment _____